

PARTS LIST		
ID	DESCRIPTION	QTY
A	Slatgrid Panel	4
B	Short Post	1
C	Long Post	1
D	Square Base	1
E	Pin (no pin on 2208)	2
F	Grooved Disk	4
G	Bearing Disk	2
H	Square Panel Hanger	2
J	Grid Clips	12
K	Sign Holder	1

- 1) Attach the Long Post (C) into the top of Square Base (D) with the screws provided.
- 2) Insert Pin (E) through holes in between rings at the top of the Square Base (Pins not required on 2208) (D).
- 3) Insert the Short Post (B) into the top of the Long Post (C) and turn counterclockwise to secure.
- 4) Insert Pin (E) through holes at the bottom of the long Post (Pins not required on 220) (C).
- 5) Place a Grooved Disk (F), a Bearing Disk (G), and then another Grooved Disk (F), through the Long Post (C) until they rest on the Pin (Pins not required on 2208) (E).
- 6) Place Square Panel Hanger (H) on top of the Disks (F-G).
- 7) Repeat steps 5-7 at top of the Short Post (B).
- 8) Take Slatgrid Panels (A) and place in pinwheel format as shown.
- 9) Connect Slatgrid Panels (A) with Grid Clips (J) as needed to secure.
- 10) Insert Sign Holder (K) into the top of Long Post (C).

